



SCREW HOLE LOCATION CHART FOR MODELS: 5100-HD AND 6100-HD






DESCRIPTION:

- All screw holes are located 1/2"
 (13) in from the outside edge of the frame.
- 2. Use the chart above to determine which screw hole location diagram applies based on the duct size of the grille or register.
- 3. This information is provided for general information only.

 Pre-drilling of mounting holes is not recommended. The actual grille or register, as supplied, should be used as a template to enhance the installation quality.



SCHEDULE TYPE:	Dimensions are in inches (mm).			
PROJECT:				
ENGINEER:	DATE	B SERIES	SUPERSEDES	DRAWING NO
CONTRACTOR:	30 - 4 - 01	SUPP./G&R	NEW	SHLC-2